

















ZESTAWIENIE STOLARKI DRZWIOWEJ

OZNACZENIA		DŁ1	D2	DŁ3	D4	D5	D6	D7	D8	D9	D10	D11	D12	D13	D14	D15															
MATERIAŁ		DRZWI DREWNIANE PŁYGINOWE								DRZWI Z OSŁONĄ RADIOLOGICZNĄ		DRZWI ALUMINIOWE																			
SCHEMAT 1:100																															
																															
wymiary w świetle ościeżnicy	S	80	80	90	90	100	120	130	120	140	90	120	90	120	90+130	150															
	H	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200															
LEWE / PRAWE		L	P	L	P	L	P	L	P	L	P	L	P	L	P	drzwi przesuwne	drzwi przesuwne														
I PIĘTRO SEGMENT B		2	1	1	—	3	5	15	17	—	1	—	1	—	1	—	4	—	1	—	1	2	1	1							
RAZEM		3		1		8		32		1		1		1		1		4		1		1		1		2		1		1	
UWAGI																															

Uwaga:  
Wymiary należy sprawdzić na budowie!

OBIEKT		Regionalny Szpital w Kołobrzegu ul. Łopuskiego 31-33 Kołobrzeg dz. 52/8 obr. 0011		DATA wrzesień 2019
NAZWA		Centrum Diagnostyki Obrazowej zestawienie stolarki drzwiowej - projekt		SKALA 1:100
PROJEKTANT		mgr inż. arch. Mikołaj Krajewski A/PB/8300/153/83		NR RYS.
SPRAWDZIŁ		mgr inż. arch. Jan Drzazga A/PB/8300/240/83		ARCHIT.